



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
May 1, 2008

Supervisor   *RM*  

<b>Mine Name:</b> Red Wolf MPI	<b>Permit Number:</b> S/039/0021
<b>Operator Name:</b> Red Wolf Development, Inc	<b>Inspection Date:</b> April 30, 2008
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 2:00 pm
<b>Other Participants:</b> Dennis Dyche	<b>Mine Status:</b> active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Routine inspection while in the area.

**Inspection Summary:**

This site was active today. Mr. Dyche was digging stone along the northern side of this area. Mr. Dyche was aware of the permitting requirements and had been told that this site was permitted and bonded (DOGM records agree with this). He was also aware that he needed to regrade disturbed areas as he progressed with his mining activity. There was less than 1/2 acre that had not been regraded. He also informed me that he had reclaimed the other Red Wolf Site (DOGM had received landowner complaint last fall) during the winter and had personally talked with the landowner, apologizing for not reclaiming when the disturbance was made.

I also collected a location point with the GPS. The location as shown on the Division's map was off by almost 2 miles.

**Conclusions and Recommendations:**

There were no compliance issues noted at this site. Continue to monitor this site when in the area.

**Inspector's Signature**   *LK*  

LK:pb

cc: Dan Wolfe, Red Wolf Development, Inc.

O:\M039-Sanpete\S0390021-RedWolfMPI\inspections\Insp-04302008.doc

080002